



DECONtamination Solution for Hexavalent Chromium Cat. No. 769-1074

Cleaning/Decontamination

1. Wet area thoroughly with DECONtamination Solution for Hexavalent Chromium. Use an abrasive pad if necessary to enhance penetration.
2. Allow the solution to react for at least 5 minutes. Rinse with water.
3. Recheck the area with Surface SWYPE for Hexavalent Chromium Cat. No. 769-1030 and Cleaning/Developing Solution for Hexavalent Chromium Cat. No. 769-1070 to verify decontamination is complete. If contamination is still present, repeat Steps 1 and 2.
4. To decontaminate tools, soak them in DECONtamination solution for at least 5 minutes and rinse with water. Recheck with Surface SWYPE to verify decontamination is complete.

SKC Limited Warranty and Return Policy

SKC products are subject to the SKC Limited Warranty and Return Policy, which provides SKC's sole liability and the buyer's exclusive remedy. To view the complete SKC Limited Warranty and Return Policy, go to skcinc.com/warranty.